

LARDIS:ONE

What should be considered when using the Motorola Rollout MR18a in combination with the MTP850 and the original CarKit?

When using a MTP850 in connection with org. carkit and LARDIS:ONE, a hotfix must be installed so that the serial communication works. With the MTP850, RTS/CTS is now active by default and cannot be set via CPS, but only with a hotfix to "Hardware Flow Control: NONE".

This hotfix is available as MTP850_MR14-MR18_No_Flow_Control_on_PEI.hfx to the respective programming departments.

Unique solution ID: #1099

Author: Tech. Support

Last update: 2023-02-10 14:22