

Are there any problems with GPS reception with heated/tinted windows?

With heated or tinted windows, there can be occasional failures with a low signal. In this case, only a GPS repeater will help, since there is no external connection for GPS antennas.

Unique solution ID: #1087

Author: Tech. Support

Last update: 2023-02-10 14:10